Newborn Screening Quality Assurance Program
Quality Control Specimen Certification
Set 2— July 14, 2014

Acylcarnitines Method: MS/MS Non-Derivatized - MS/MS non-kit

ENRICHMENT LEVELS (endogenous levels not included)

Analyte (µmol/L whole blood)	Lot	Base	Lot	Low	Lot	Intermediate	Lot	High
Free carnitine (C0)	1461	0	1462	10.0	1463	20.0	1464	30.0
Acetylcarnitine (C2)	1461	0	1462	10.0	1463	20.0	1464	30.0
Propionylcarnitine (C3)	1461	0	1462	3.0	1463	7.5	1464	12.0
Butyrylcarnitine (C4)	1461	0	1462	1.0	1463	2.5	1464	5.0
Malonylcarnitine + Hydroxybutyrylcarnitine (C3DC + C4OH)	1461	0	1462	1.0	1463	2.5	1464	5.5
Isovalerylcarnitine (C5)	1461	0	1462	0.5	1463	1.5	1464	3.0
Glutarylcarnitine (C5DC)	1461	0	1462	0.5	1463	1.0	1464	2.5
Hydroxyisovalerylcarnitine (C5OH)	1461	0	1462	0.5	1463	1.5	1464	2.5
Hexanoylcarnitine (C6)	1461	0	1462	0.5	1463	1.0	1464	2.5
Octanoylcarnitine (C8)	1461	0	1462	0.5	1463	1.0	1464	2.5
Decanoylcarnitine (C10)	1461	0	1462	0.5	1463	1.0	1464	2.5
Dodecanoylcarnitine (C12)	1461	0	1462	0.5	1463	1.0	1464	2.5
Myristoylcarnitine (C14)	1461	0	1462	0.5	1463	1.5	1464	3.0
Palmitoylcarnitine (C16)	1461	0	1462	3.0	1463	8.0	1464	12.0
Hydroxypalmitoylcarnitine (C16OH)	1461	0	1462	0.1	1463	0.5	1464	1.0
Stearoylcarnitine (C18)	1461	0	1462	1.0	1463	2.0	1464	5.0
Hydroxystearoylcarnitine (C18OH)	1461	0	1462	0.5	1463	1.0	1464	1.5

Newborn Screening Quality Assurance Program

Quality Control Specimen Certification Set 2— July 14, 2014

Acylcarnitines Method: MS/MS Non-Derivatized - MS/MS non-kit

ANALYTICAL INFORMATION Lot Numbers, Mean Values (x, µmol/L whole blood), and 95% Confidence Limits (CL)

Analyte	Lot	Mean/ 95% CL						
C0	1461	$\bar{x} = 13.0$ CL = 11.2–14.7	1462	$\bar{x} = 21.1$ CL = 18.6-23.6	1463	$\bar{x} = 29.3$ CL = 25.9-32.6	1464	$\bar{x} = 38.1$ CL = 33.1-43.1
C2	1461	$\bar{x} = 12.4$ CL = 11.0-13.7	1462	$\bar{x} = 22.0$ CL = 19.4-24.6	1463	$\bar{x} = 32.2$ CL = 28.6-35.9	1464	$\bar{x} = 41.8$ CL = 36.4-47.2
C3	1461	$\bar{x} = 1.2$ CL = 0.9–1.5	1462	$\bar{x} = 3.9$ CL = 3.1-4.8	1463	$\bar{x} = 7.9$ CL = 5.5-10.2	1464	$\bar{x} = 11.6$ CL = 8.9-14.3
C4	1461	$\bar{x} = 0.1$ CL = 0.1–0.2	1462	$\bar{x} = 1.0$ CL = 0.7-1.2	1463	$\bar{x} = 2.2$ CL = 1.8–2.7	1464	$\bar{x} = 4.4$ CL = 3.2–5.5
C3DC + C4OH	1461	$\bar{x} = 0.1$ CL = 0.0–0.1	1462	$\bar{x} = 0.3$ CL = 0.2-0.4	1463	$\bar{x} = 0.5$ CL = 0.4-0.7	1464	$\bar{x} = 1.1$ CL = 0.8-1.4
C5	1461	$\bar{x} = 0.1$ CL = 0.1–0.1	1462	$\bar{x} = 0.6$ CL = 0.4–0.7	1463	$\bar{x} = 1.4$ CL = 1.1–1.7	1464	$\bar{x} = 2.7$ CL = 2.1–3.3
C5DC	1461	$\bar{x} = 0.1$ CL = 0.0–0.2	1462	$\bar{x} = 0.7$ CL = 0.4–1.0	1463	$\bar{x} = 1.2$ CL = 0.7-1.8	1464	$\bar{x} = 2.8$ CL = 2.0-3.6
С5ОН	1461	$\bar{x} = 0.8$ CL = 0.5-1.0	1462	$\bar{x} = 1.2$ CL = 0.8–1.6	1463	$\bar{x} = 2.1$ CL = 1.4–2.8	1464	$\bar{x} = 3.1$ CL = 2.4–3.9
C6	1461	$\bar{x} = 0.0$ CL = 0.0–0.1	1462	$\bar{x} = 0.5$ CL = 0.3-0.6	1463	$\bar{x} = 0.9$ CL = 0.7–1.2	1464	$\bar{x} = 2.2$ CL = 1.8–2.7
C8	1461	$\bar{x} = 0.0$ CL = 0.0–0.1	1462	$\bar{x} = 0.6$ CL = 0.4–0.8	1463	$\bar{x} = 1.1$ CL = 0.9–1.4	1464	$\bar{x} = 2.6$ CL = 2.0-3.1
C10	1461	$\bar{x} = 0.1$ CL = 0.0–0.1	1462	$\bar{x} = 0.7$ CL = 0.4–0.9	1463	$\bar{x} = 1.1$ CL = 0.8–1.3	1464	$\bar{x} = 2.7$ CL = 2.0-3.4
C12	1461	$\bar{x} = 0.0$ CL = 0.0–0.0	1462	$\bar{x} = 0.4$ CL = 0.4–0.5	1463	$\bar{x} = 0.9$ CL = 0.7–1.1	1464	$\bar{x} = 2.2$ CL = 1.7–2.8
C14	1461	$\bar{x} = 0.1$ CL = 0.0–0.1	1462	$\bar{x} = 0.6$ CL = 0.4–0.7	1463	$\bar{x} = 1.4$ CL = 1.1–1.7	1464	$\bar{x} = 2.8$ CL = 2.2–3.5
C16	1461	$\bar{x} = 1.0$ CL = 0.8–1.1	1462	$\bar{x} = 3.3$ CL = 2.6–3.9	1463	$\bar{x} = 7.2$ CL = 5.6–8.8	1464	$\bar{x} = 10.0$ CL = 7.9–12.1
С16ОН	1461	$\bar{x} = 0.0$ CL = 0.0–0.0	1462	$\bar{x} = 0.1$ CL = 0.0-0.1	1463	$\bar{x} = 0.3$ CL = 0.2–0.4	1464	$\bar{x} = 0.5$ CL = 0.3–0.7
C18	1461	$\bar{x} = 0.7$ CL = 0.5–0.9	1462	$\bar{x} = 1.5$ CL = 1.1–2.0	1463	$\bar{x} = 2.3$ CL = 1.8–2.8	1464	$\bar{x} = 4.9$ CL = 3.7-6.0
С18ОН	1461	$\bar{x} = 0.0$ CL = 0.0–0.0	1462	$\bar{x} = 0.3$ CL = 0.1–0.4	1463	$\bar{x} = 0.5$ CL = 0.2–0.8	1464	$\bar{x} = 0.8$ CL = 0.3-1.2

Note: The values provided in the above tables are for reference use only. The mean value and confidence limits (CL) are determined by CDC for each Quality Control (QC) lot. Each participating laboratory must establish its own mean values and CL for its test method with these QC materials. Temporary estimates of mean values and CL can be determined after 10 successive, independent measurements. Slazyk WE, Hannon WH. Quality assurance in the newborn screening laboratory. In: Therrell BL Jr, editor. Laboratory methods for neonatal screening. Washington (DC): American Public Health Association, 1993:23-46.

Newborn Screening Quality Assurance Program
Quality Control Specimen Certification
Transition Set

Acylcarnitines Method: MS/MS Non-Derivatized - MS/MS non-kit

ENRICHMENT LEVELS (endogenous levels not included)

Analyte (µmol/L whole blood)	Lot	Base	Lot	Low	Lot	Intermediate	Lot	High
Free carnitine (C0)	1365	0	1366	10.0	1367	20.0	1368	30.0
Acetylcarnitine (C2)	1365	0	1366	10.0	1367	20.0	1368	30.0
Propionylcarnitine (C3)	1365	0	1366	3.0	1367	7.5	1368	12.0
Butyrylcarnitine (C4)	1365	0	1366	1.0	1367	2.5	1368	5.0
Malonylcarnitine + Hydroxybutyrylcarnitine (C3DC + C4OH)	1365	0	1366	1.0	1367	2.5	1368	5.5
Isovalerylcarnitine (C5)	1365	0	1366	0.5	1367	1.5	1368	3.0
Glutarylcarnitine (C5DC)	1365	0	1366	0.5	1367	1.0	1368	2.5
Hydroxyisovalerylcarnitine (C5OH)	1365	0	1366	0.5	1367	1.5	1368	2.5
Hexanoylcarnitine (C6)	1365	0	1366	0.5	1367	1.0	1368	2.5
Octanoylcarnitine (C8)	1365	0	1366	0.5	1367	1.0	1368	2.5
Decanoylcarnitine (C10)	1365	0	1366	0.5	1367	1.0	1368	2.5
Dodecanoylcarnitine (C12)	1365	0	1366	0.5	1367	1.0	1368	2.5
Myristoylcarnitine (C14)	1365	0	1366	0.5	1367	1.5	1368	3.0
Palmitoylcarnitine (C16)	1365	0	1366	3.0	1367	8.0	1368	12.0
Hydroxypalmitoylcarnitine (C16OH)	1365	0	1366	0.1	1367	0.5	1368	1.0
Stearoylcarnitine (C18)	1365	0	1366	1.0	1367	2.0	1368	5.0
Hydroxystearoylcarnitine (C18OH)	1365	0	1366	0.1	1367	0.5	1368	1.0

Newborn Screening Quality Assurance Program

Quality Control Specimen Certification Transition Set

Acylcarnitines Method: MS/MS Non-Derivatized - MS/MS non-kit

ANALYTICAL INFORMATION Lot Numbers, Mean Values (x, µmol/L whole blood), and 95% Confidence Limits (CL)

	INALIII	CAL INFORMATION	Loi Ivamo	ers, mean values (A, p	moul w	note bioba), and 7570 C	onjiuenc	e Linus (CL)
Analyte	Lot	Mean/ 95% CL	Lot	Mean/ 95% CL	Lot	Mean/ 95% CL	Lot	Mean/ 95% CL
C0	1365	$\bar{x} = 15.7$ CL = 12.8–18.6	1366	$\bar{x} = 18.3$ CL = 13.8–22.7	1367	$\bar{x} = 30.8$ CL = 24.3–37.3	1368	$\bar{x} = 41.7$ CL = 32.9–50.5
C2	1365	$\bar{x} = 10.5$ CL = 9.2–11.8	1366	$\bar{x} = 20.3$ CL = 16.8–23.8	1367	$\bar{x} = 29.6$ CL = 25.0-34.3	1368	$\bar{x} = 40.6$ CL = 32.6–48.5
C3	1365	$\bar{x} = 1.3$ CL = 0.9–1.6	1366	$\bar{x} = 4.0$ CL = 3.1–4.9	1367	$\bar{x} = 8.0$ CL = 4.9–11.0	1368	$\bar{x} = 12.1$ CL = 9.3–15.0
C4	1365	$\bar{x} = 0.2$ CL = 0.1–0.2	1366	$\bar{x} = 1.0$ CL = 0.7-1.3	1367	$\bar{x} = 2.1$ CL = 1.4–2.8	1368	$\bar{x} = 4.2$ CL = 2.9–5.5
C3DC + C4OH	1365	$\bar{x} = 0.3$ CL = 0.1–0.5	1366	$\bar{x} = 1.3$ CL = 0.5-2.0	1367	$\bar{x} = 2.2$ CL = 1.2–3.2	1368	$\bar{x} = 5.1$ CL = 2.6–7.5
C5	1365	$\bar{x} = 0.1$ CL = 0.1–0.2	1366	$\bar{x} = 0.6$ CL = 0.4–0.7	1367	$\bar{x} = 1.4$ CL = 1.0–1.9	1368	$\bar{x} = 2.9$ CL = 2.1–3.8
C5DC	1365	$\bar{x} = 0.0$ CL = 0.0–0.1	1366	$\bar{x} = 0.5$ CL = 0.3-0.8	1367	$\bar{x} = 0.9$ CL = 0.5-1.3	1368	$\bar{x} = 2.3$ CL = 1.1–3.5
С5ОН	1365	$\bar{x} = 0.7$ CL = 0.4–1.0	1366	$\bar{x} = 1.1$ CL = 0.8–1.4	1367	$\bar{x} = 1.8$ CL = 1.2–2.4	1368	$\bar{x} = 2.8$ CL = 1.8–3.9
C6	1365	$\bar{x} = 0.0$ CL = 0.0–0.1	1366	$\bar{x} = 0.5$ CL = 0.3-0.6	1367	$\bar{x} = 0.8$ CL = 0.6-1.1	1368	$\bar{x} = 2.2$ CL = 1.5–2.9
C8	1365	$\bar{x} = 0.0$ CL = 0.0–0.1	1366	$\bar{x} = 0.5$ CL = 0.3-0.7	1367	$\bar{x} = 0.9$ CL = 0.6–1.2	1368	$\bar{x} = 2.3$ CL = 1.7–2.8
C10	1365	$\bar{x} = 0.0$ CL = 0.0–0.1	1366	$\bar{x} = 0.5$ CL = 0.3-0.6	1367	$\bar{x} = 0.8$ CL = 0.6-1.1	1368	$\bar{x} = 2.2$ CL = 1.5–2.9
C12	1365	$\bar{x} = 0.0$ CL = 0.0–0.0	1366	$\bar{x} = 0.4$ CL = 0.3-0.6	1367	$\bar{x} = 0.8$ CL = 0.6-1.1	1368	$\bar{x} = 2.5$ CL = 1.6–3.3
C14	1365	$\bar{x} = 0.1$ CL = 0.0–0.1	1366	$\bar{x} = 0.5$ CL = 0.3–0.7	1367	$\bar{x} = 1.4$ CL = 1.0–1.8	1368	$\bar{x} = 2.8$ CL = 1.9–3.8
C16	1365	$\bar{x} = 0.8$ CL = 0.6–1.0	1366	$\bar{x} = 3.3$ CL = 2.6–4.1	1367	$\bar{x} = 7.3$ CL = 5.6–9.0	1368	$\bar{x} = 11.1$ CL = 9.0–13.2
С16ОН	1365	$\bar{x} = 0.0$ CL = 0.0–0.0	1366	$\bar{x} = 0.0$ CL = 0.0–0.1	1367	$\bar{x} = 0.2$ CL = 0.1–0.2	1368	$\bar{x} = 0.3$ CL = 0.2–0.5
C18	1365	$\bar{x} = 0.7$ CL = 0.5–0.9	1366	$\bar{x} = 1.5$ CL = 1.1–1.9	1367	$\bar{x} = 2.3$ CL = 1.7–3.0	1368	$\bar{x} = 5.3$ CL = 4.0–6.6
С18ОН	1365	$\bar{x} = 0.0$ CL = 0.0-0.0	1366	$\bar{x} = 0.2$ CL = 0.1–0.2	1367	$\bar{x} = 0.3$ CL = 0.2–0.4	1368	$\bar{x} = 0.5$ CL = 0.3-0.7

Note: The values provided in the above tables are for reference use only. The mean value and confidence limits (CL) are determined by CDC for each Quality Control (QC) lot. Each participating laboratory must establish its own mean values and CL for its test method with these QC materials. Temporary estimates of mean values and CL can be determined after 10 successive, independent measurements. Slazyk WE, Hannon WH. Quality assurance in the newborn screening laboratory. In: Therrell BL Jr, editor. Laboratory methods for neonatal screening. Washington (DC): American Public Health Association, 1993:23-46.